Weathertzsiton Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: 13013SH2378Work Order Type: WeatherizationAudit Name: 13013SH2378

CLIENT INFORMATION

Client ID: 13013SH2378

AGENCY INFORMATION

Client ID: 13013SH2378

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: WOOD, JIM Work Phone:

Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Measures

Measure	l Floo	r Ins. R-19			Componen	ts F1		ı	Inspected
Comment	FLOOR	INSULATION NEEDED	R-19 1194	4 SQ F	Т				
					Estimated	<u> </u>		Actual	
# Material / L	abor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation		Floor Insulation - Fiberglass Batts - R-19	SqFt	1194					
2 Labor		Floor Insulation - Fiberglass Batts - R-19	SqFt	1194					
Other Detail									
				Measure	e Sub Total:			Sub Total:	
Field Notes	S:								
Measure :		igerator Rplcmnt			Componen	nts		1	Inspected
		igerator Rplcmnt CE 20 CU FT REFRIGER	RATOR		-				Inspected
Comment	REPLAC	CE 20 CU FT REFRIGER			Estimated	<u> </u>		Actual	
Comment # Material / I	REPLA(.abor	Description / Comment	Units	Qty	-		Qty		Inspected Total
Comment	REPLA(.abor	CE 20 CU FT REFRIGER			Estimated	<u> </u>	Qty	Actual	
Comment # Material / I	REPLA(.abor	Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
# Material / I 1 Refrigerat	REPLA(.abor	Description / Comment ANY - ANY	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / I 1 Refrigerat 2 Labor	REPLA(.abor	Description / Comment ANY - ANY	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / I 1 Refrigerat 2 Labor	REPLA(.abor	Description / Comment ANY - ANY	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / I 1 Refrigerat 2 Labor	REPLA(.abor	Description / Comment ANY - ANY	Units Each Each	Qty 1 1	Estimated	<u> </u>		Actual	
# Material / I 1 Refrigerat 2 Labor	REPLAC -abor ors	Description / Comment ANY - ANY	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / I 1 Refrigerat 2 Labor Other Detail	REPLAC -abor ors	Description / Comment ANY - ANY	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / I 1 Refrigerat 2 Labor Other Detail	REPLAC -abor ors	Description / Comment ANY - ANY	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

-	Measure 3 Repl	ace Htg. System			Componen	its 1			Inspected
C		CE HEATING SYSTEM ONTAL UNIT 75,000 BT		Έ					
					Estimated	<u>'</u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipmen	Replacement Furnace (not used) - 75 kBtu/h NG Existing, 113-158 kBtu/h NG Post	Each	1					
2	Labor	Replacement Furnace (not used) - 75 kBtu/h NG Existing, 113-158 kBtu/h NG Post	Each	1					
C	Other Detail								
				Measur	e Sub Total:]	Sub Total:	
	Measure 4 CO N	Monitor is Needed			Componen	nts			Inspected
Ŭ	omment.				Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	-	Each	1					
2	Labor	Labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:]	Sub Total:	
	Field Notes:								

Measure 5 Fix A	em	Components				Inspected		
Comment REVEN	Γ W/H 15 FT THRU ROC)F						
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measu	re Sub Total:] ;	Sub Total:	
	mproper Venting (Cloth)	Componen			Actual	Inspected
# Material / Labor	Description / Comment	Units	O41/	Unit Cost	Total	O4v	Unit Cost	Total
1 Health and Safety	Description / Comment Equipment	Each	Qty 1	Omit Cost	TOTAL	Qty	Unit Cost	TOTAL
2 Labor	Labor	Each	1					
Other Detail								
			Measu	re Sub Total:			Sub Total:	

	Measure 7 Pres	sureRelief Piping Need	ded		Componen	ts			Inspected
C	comment REPLAC	E DROP ON T&P VALV	/E						
					Estimated	<u>'</u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Pressure relief piping	Each	1					
2	Labor	Labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
I	•	or Barrier Needed			Componen	ts			Inspected
C	comment GROUN	ement/CrawIspace) D COVER NEEDED 119 SPACE DOOR UNIT (22		TO INC	CLUDE REP	LACE			
					Estimated	<u> </u>		Actual	
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total			
1				Qty	Omit Cost	Total	Qty	Unit Cost	Total
٠	Health and Safety		SqFt	1194	Omit Cost	TOTAL	Qty	Unit Cost	Total
	Labor	Basement / crawlspace	SqFt SqFt			Total	Qty	Unit Cost	Total
2		Basement / crawlspace vapor barrier		1194		Total	Qty	Unit Cost	Total
2	Labor	Basement / crawlspace vapor barrier		1194		Total	Qty	Unit Cost	Total
2	Labor	Basement / crawlspace vapor barrier		1194		Total		Unit Cost	Total
2	Labor	Basement / crawlspace vapor barrier	SqFt	1194	e Sub Total:	Total		Unit Cost	Total
2	Labor	Basement / crawlspace vapor barrier	SqFt	1194		Total			Total

Client ID: 13013SH2378